

It is in reference to Institute Open Tender no. *OT-26/MNNIT/Purchase Office/CED/Lab Equipments (UG Lab)/2013-14* Date: 08.02.2013, for procurement of 'Various Lab Equipments'.

The schedule of price bid opening is as follows:

Date: 01.05.2013 (Wednesday)

Time: at 15:00 hrs.

Venue: Institute Conference Room

The detailed list of NON-RESPONSIVE (alongwith reasons) and RESPONSIVE bidders are available at MNNIT website: <http://www.mnnit.ac.in/tenders.html>

Regards

अशोक
23.04.2013

Faculty In-charge (Purchase)
MNNIT Allahabad

Tender Enquiry No. OT-26/MNNIT/Purchase Office/CED/Lab equipments (UG Lab)/2013-14 Date: 08.02.2013

List of Bidders बोलीदाताओं की सूची

SI. No	For items आइटम के लिए	Name & Address of Bidder(s) बोलीदाता(ओं) का नाम व पता
1.	Arc Pad	1. M/S Aimil Ltd. New Delhi
2.	Auto Level	1. M/S Aimil Ltd. New Delhi
3.	GPS Hand Held	1. M/S Aimil Ltd. New Delhi
4.	Total Station (Reflectorless)	1. M/S Aimil Ltd. New Delhi

(A.) List of Bidders Found NON –RESPONSIVE (along with reasons) in Technical Bid (Part-I) Evaluation तकनीकी बोली (भाग-1) मूल्यांकन में अनुत्तरदायी (कारणों के साथ) पाए गए बोलीदाताओं की सूची

SI. No	For items आइटम के लिए	Name & Address of Bidder(s) बोलीदाता(ओं) का नाम व पता
1.	Auto Level	M/S Aimil Ltd. New Delhi

Reasons for being NON –RESPONSIVE अनुत्तरदायी होने के कारण

SI.NO	Point in Tender Document निविदा दस्तावेज में बिंदु	Reasons कारण	
	Reasons as per technical Specifications तकनीकी निर्दिष्टीकरण के अनुसार कारण		
SI No.	Points as per Tender Document निविदा दस्तावेज के अनुरूप बिंदु	Technical Specification Required आवश्यक तकनीकी निर्दिष्टीकरण	Technical Specification Offered By Bidder बोलीदाता द्वारा प्रस्तुत तकनीकी निर्दिष्टीकरण
	SI No. 2 on page 32/69 Auto Level	Auto Level	Authorization certificate from original manufacturer as per clause no. 21 in Annexure C not submitted.


(B.) List of Bidders Found RESPONSIVE in Technical Bid (Part-I) Evaluation तकनीकी बोली (भाग-1) मूल्यांकन में उत्तरदायी पाए गए बोलीदाताओं की सूची


SI No	For Items आइटम के लिए	Name & Address of Bidder(s) बोलीदाता(ओं) का नाम व पता
1	Total Station (Reflectorless)	1. M/S Aimil Ltd. New Delhi
2	GPS Hand Held	1. M/S Aimil Ltd. New Delhi
4	Arc Pad	1. M/S Aimil Ltd. New Delhi


The following observation was made in the case of Annexure-C (Special Technical Terms & Conditions) submitted by M/S AIMIL LTD.

SI. No..	Point in Tender Document निविदा दस्तावेज में बिंदु	Reasons कारण
1	Point No. 11 Page No. 16/69	AIMIL has accepted the payment conditions as per GCC 22.1 Clause 16(i).

Therefore, the procurement of equipments may be considered from AIMIL LTD. after proper attention to the above mentioned points at the time of opening of Financial Bid.


(R.P. Singh)
Professor


(A. K. Sachan)
Professor


(R. P. Tiwari)
Professor & Head

REFERENCE: OT-26/MNNIT/PURCHASE OFFICE/CED/Lab Equipments (UG Lab)/ /2013-14 Dated 08.02.2013 due on 04.03.2013

List of Bidders found NON-RESPONSIVE (along with reasons) In Technical Bid (Part-I) Evaluation

तकनीकी बोली (भाग-1) मूल्यांकन में अनुत्तरदायी (कारणों के साथ) पाए गए बोलीदाताओं की सूची

Sl. No./ Item No.	For Items	आइटम के लिए	Name & Address of Bidder(s) बोलीदाता(ओं) का नाम व पता
1	SLUMP TEST APPARATUS		<p style="text-align: center;">HEICO A-13, Naraina Industrial Area, Phase-II, New Delhi-110028</p>
2	COMPACTION FACTOR APPARATUS		
3	CONSISTOMETER		
4	CONCRETE MIXER		
5	CONCRETE MIXER PAN TYPE		
6	HYDRAULIC JACK 50 kN		
7	HYDRAULIC JACK 250 kN		
8	HYDRAULIC JACK 500 kN		
9	VICAT APPARATUS (2)		
10	CEMENT AUTOCLAVE		
11	CEMENT TENSILE TESTING MACHINE		
12	CRUSHING VALUE APPARATUS		
13	AGGREGATE IMPACT TESTER		
14	LOS ANGELS ABRASION TESTING MACHINE		
15	BEAM MOULD (3)		
16	ULTRASONIC PULSE VELOCITY METER		
17	SIEVE (20)		

Sl. No./ Item No.	For Items	आइटम के लिए	Name & Address of Bidder(s) बोलीदाता(ओं) का नाम व पता
1	A. 85: ULTRASONIC PULSE VELOCITY METER		<p style="text-align: center;">AIMIL LIMITED, Naimex House, A-8, Mohan Cooperative Industrial Estate, Mathura Road, New Delhi – 110044</p>

Reasons for being NON-RESPONSIVE अनुत्तरदायी होने के कारण

Sl. No.	Point in Tender Document	निविदा दस्तावेज में बिंदु	Reasons	कारण
1.	A. 70: SLUMP TEST APPARATUS A. 72: CONSISTOMETER A. 73: CONCRETE MIXER A. 74: CONCRETE MIXER PAN TYPE A. 79: CEMENT AUTOCLAVE A. 80: CEMENT TENSILE TESTING MACHINE A. 85: ULTRASONIC PULSE VELOCITY METER		HEICO does not comply STC Clause (4).	
2.	A. 71: COMPACTION FACTOR APPARATUS A. 75: HYDRAULIC JACK 50 kN A. 76: HYDRAULIC JACK 250 kN A. 77: HYDRAULIC JACK 500 kN A. 78: VICAT APPARATUS (2) A. 81: CRUSHING VALUE APPARATUS A. 82: AGGREGATE IMPACT TESTER A. 83: LOS ANGELS ABRASION TESTING MACHINE A. 84: BEAM MOULD (3) A. 86: SIEVE (20)			
3.	A. 85: ULTRASONIC PULSE VELOCITY METER		AIMIL LTD. has not quoted the item.	

[Signature]
23/3/13

[Signature]
23/3
[1/2]

[Signature]
23/3/13

Reasons as per Technical Specifications		तकनीकीनिर्दिष्टीकरणकेअनुसारकारण	
Sl. No.	Points as per Tender Document	Technical Specifications Required	Technical Specifications offered by Bidder
	निविदादस्तावेजकेअनुरूपबिंदु	आवश्यकतकनीकीनिर्दिष्टीकरण	बोलीदाताद्वाराप्रस्तुततकनीकीनिर्दिष्टीकरण
	NA	NA	NA

(A) List of Bidders found RESPONSIVE in Technical Bid (Part-I) Evaluation


तकनीकीबोली(भाग-1) मूल्यांकनमेंउत्तरदायीपाएगएबोलीदाताओंकीसूची


Sl. No.	For Items	आइटमकेलिए	Name & Address of Bidder(s) बोलीदाता(ओं) कानामवपता
1	SLUMP TEST APPARATUS		<p style="text-align: center;">AIMIL LIMITED, Naimex House, A-8, Mohan Cooperative Industrial Estate, Mathura Road, New Delhi – 110044</p>
2	COMPACTION FACTOR APPARATUS		
3	CONSISTOMETER		
4	CONCRETE MIXER		
5	CONCRETE MIXER PAN TYPE		
6	HYDRAULIC JACK 50 kN		
7	HYDRAULIC JACK 250 kN		
8	HYDRAULIC JACK 500 kN		
9	VICAT APPARATUS (2)		
10	CEMENT AUTOCLAVE		
11	CEMENT TENSILE TESTING MACHINE		
12	CRUSHING VALUE APPARATUS		
13	AGGREGATE IMPACT TESTER		
14	LOS ANGELS ABRASION TESTING MACHINE		
15	BEAM MOULD (3)		
16	SIEVE (20)		


The following observation was made in the case of Annexure-C (Special Technical Terms & Conditions) submitted by M/S AIMIL LTD.

Sl. No..	Point in Tender Document निविदा दस्तावेज में बिंदु	Reasons	कारण
1	Point No. 11 Page No. 16/69	AIMIL has accepted the payment conditions as per GCC 22.1 Clause 16(i).	

Therefore, the procurement of equipments may be considered from AIMIL LTD. after proper attention to the above mentioned point at the time of opening of Financial Bid.


(R.P. Singh)
Professor


(A. K. Sachan)
Professor


(R. P. Tiwari)
Professor & Head

REFERENCE: OT-26/MNNIT/PURCHASE OFFICE/CED/Lab Equipments (UG Lab)/ 2013-14 Dated 08.02.2013 due on 04.03.2013

List of Bidders found NON-RESPONSIVE (along with reasons) In Technical Bid (Part-I) Evaluation

तकनीकी बोली (भाग-I) मूल्यांकन में अनुत्तरदायी (कारणों के साथ) पाए गए बोलीदाताओं की सूची

Sl. No.	Name & Address of Bidder(s) बोलीदाता (ओं) का नाम व पता
1.	HEICO, A-13, Naraina Industrial Area, Phase-II, New Delhi-110028

Reasons for being NON-RESPONSIVE अनुत्तरदायी होने के कारण

Sl. No.	Point in Tender Document निविदा दस्तावेज में बिंदु	Name & Address of Bidder(s) बोलीदाता (ओं) का नाम व पता
	In Tender Document	
1	Specific Technical Conditions : Point No 4 (Page no 16/69)	HEICO does not comply STC Clause (4). HEICO, A-13, Naraina Industrial Area, Phase-II, New Delhi-110028

List of Bidders found NON-RESPONSIVE (along with reasons) In Technical Bid (Part-I) Evaluation

तकनीकी बोली (भाग-I) मूल्यांकन में अनुत्तरदायी (कारणों के साथ) पाए गए बोलीदाताओं की सूची

Sl. No.	For Items आइटम के लिए	Name & Address of Bidder(s) बोलीदाता (ओं) का नाम व पता
1.	A7: Density Bottle	AIMIL LIMITED, Naimex House, A-8, Mohan Cooperative Industrial Estate, Mathura Road, New Delhi – 110044
2.	A8: Sand Density Cone	
3.	A28: Hydrometer bulb	
4.	A30: Weighing Machine (Capacity 10 kg)	
5.	A31: Weighing Machine (Capacity 30 kg)	

Reasons as per Technical Specifications तकनीकी निर्दिष्टीकरण के अनुसार कारण

Sl. No.	Points as per Tender Document निविदा दस्तावेज के अनुरूप बिंदु	Technical Specifications Required आवश्यक तकनीकी निर्दिष्टीकरण	Technical Specifications offered by Bidder बोलीदाता द्वारा प्रस्तुत तकनीकी निर्दिष्टीकरण
1.	A7: Density Bottle	NA	Not Quoted
2.	A8: Sand Density Cone	NA	Not Quoted
3.	A28: Hydrometer bulb	NA	Not Quoted
4.	A30: Weighing Machine (Capacity 10 kg)	NA	Not Quoted
5.	A31: Weighing Machine (Capacity 30 kg)	NA	Not Quoted

Sp/1
28/3/13

May
23/3

Hasan
23/3/13

(A.) List of Bidders found **RESPONSIVE** in Technical Bid (Part-I) Evaluation


तकनीकी बोली (भाग-I) मूल्यांकन में उत्तरदायी पाए गए बोलीदाताओं की सूची


Sl. No.	For Items आइटम के लिए	Name & Address of Bidder(s) बोलीदाता(ओं) का नाम व पता
1.	A1: Liquid Limit Device, Motorized	AIMIL LIMITED, Naimex House, A-8, Mohan Cooperative Industrial Estate, Mathura Road, New Delhi – 110044
2.	A2: Shrinkage Limit Apparatus	
3.	A3: Sand Pouring Cylinder (Small)	
4.	A4: Core Cutter	
5.	A5: Sand Pouring Cylinder, (Large)	
6.	A6: Pycnometer	
7.	A9: CBR test	
8.	A10: Swell Pressure Test Apparatus	
9.	A11: Standard Penetration Test (SPT) apparatus with accessories	
10.	A12: Compaction Mould (Light)	
11.	A13: Rammer (Light Weight)	
12.	A14: Compaction Mould (Heavy)	
13.	A15: Rammer (Heavy Weight)	
14.	A16: Grain size distribution by Pipette Method	
15.	A17: Permeability test: constant head	
16.	A18: Permeability test: variable head	
17.	A19: Dynamic cone penetration Tests	
18.	A20: Plate load test	
19.	A21: Compaction Permeameter Mould	
20.	A22: Direct Shear Apparatus	
21.	A23: Sieve Shaker Motorised with Digital Counter	
22.	A24: Sample extractor	
23.	A25: Triaxial test	
24.	A26: CBR Mould	
25.	A27: Consolidation	
26.	A29: Fine grain analysis	


The following observation was made in the case of Annexure-C (Special Technical Terms & Conditions) submitted by M/S AIMIL LTD.

Sl. No..	Point in Tender Document निविदा दस्तावेज में बिंदु	Reasons कारण
1	Point No. 11 Page No. 16/69	AIMIL has accepted the payment conditions as per GCC 22.1 Clause 16(i).

Therefore, the procurement of equipments may be considered from AIMIL LTD. after proper attention to the above mentioned point at the time of opening of Financial Bid.


(R.P. Singh)
Professor


(A. K. Sachan)
Professor


(R. P. Tiwari)
Professor & Head

Open Tender No. OT-26/MNNIT/Purchase Office/CED/LAB EQUIPMENT (UG LAB)/2013-14 Dated 08/02/2013

List of Bidders found NON-RESPONSIVE (along with reasons) In Technical Bid (Part-I) Evaluation

तकनीकी बोली (भाग-I) मूल्यांकन में अनुत्तरदायी (कारणों के साथ) पाए गए बोलीदाताओं की सूची

Sl. No.	For Items आइटम के लिए	Name & Address of Bidder(s) बोलीदाता(ओं) का नाम व पता
1	Crushing Value Apparatus	HEICO, A-13, Naraina Industrial Area, Phase-II, New Delhi-110028 Fax: 91-011-25893152 E-mail: info@heicoind.com
2	Aggregate Impact Tester with Automatic Blow Counter	
3	Los Angeles Abrasion testing machine with Counter	
4	Thickness Gauge	
5	Length Gauge	
6	Universal Penetrometer	
7	Ring and Ball Apparatus**	
8	Ductility Testing Machine with digital display	
9	Flash Point (Closed) Pensky-Martens Apparatus**	
10	Flash Point (Open) and Fire Point, Pensky-Martens Apparatus**	
11	Standard tar viscometer**	
12	Engler Viscometer	
13	Digital Marshall Apparatus	

**Remarks: HEICO, New Delhi did not quote for Ring and Ball Apparatus, Flash Point (Closed) Pensky-Martens Apparatus, Flash Point (Open) and Fire Point, Pensky-Martens Apparatus, Standard tar viscometer and Engler Viscometer.

Reasons for being NON-RESPONSIVE

अनुत्तरदायी होने के कारण

Sl. No.	Point in Tender Document निविदा दस्तावेज में बिंदु	Reasons कारण
1	Specific Technical Conditions : Point No 4 (Page no 16/69)	HEICO does not comply STC Clause (4).

Reasons as per Technical Specifications		तकनीकी निर्दिष्टीकरण के अनुसार कारण	
Sl. No.	Points as per Tender Document निविदा दस्तावेज के अनुरूप बिंदु	Technical Specifications Required आवश्यक तकनीकी निर्दिष्टीकरण	Technical Specifications offered by Bidder बोलीदाता द्वारा प्रस्तुत तकनीकी निर्दिष्टीकरण
1.	Specific Technical Conditions: Point No 4 (Page no 16/69)	Crushing Value Apparatus	HEICO does not comply STC Clause (4).
2.	Specific Technical Conditions: Point No 4 (Page no 16/69)	Aggregate Impact Tester with Automatic Blow Counter	HEICO does not comply STC Clause (4).

[Signature]
23/3/13

[Signature]
23/3

[Signature]
23/3/13

3.	Specific Technical Conditions: Point No 4 (Page no 16/69)	Los Angeles Abrasion testing machine with Counter	HEICO does not comply STC Clause (4).
4.	Specific Technical Conditions: Point No 4 (Page no 16/69)	Thickness Gauge	HEICO does not comply STC Clause (4).
5.	Specific Technical Conditions: Point No 4 (Page no 16/69)	Length Gauge	HEICO does not comply STC Clause (4).
6.	Specific Technical Conditions: Point No 4 (Page no 16/69)	Universal Penetrometer	HEICO does not comply STC Clause (4).
7.	**	Ring and Ball Apparatus	**
8.	Specific Technical Conditions: Point No 4 (Page no 16/69)	Ductility Testing Machine with digital display	HEICO does not comply STC Clause (4).
9.	**	Flash Point (Closed) Pensky-Martens Apparatus	**
10.	**	Flash Point (Open) and Fire Point, Pensky-Martens Apparatus	**
11.	**	Standard tar viscometer	**
12.	**	Engler Viscometer	**
13.	Specific Technical Conditions: Point No 4 (Page no 16/69)	Digital Marshall Apparatus	HEICO does not comply STC Clause (4).

**Remarks: HEICO, New Delhi did not quote for Ring and Ball Apparatus, Flash Point (Closed) Pensky-Martens Apparatus, Flash Point (Open) and Fire Point, Pensky-Martens Apparatus Standard tar viscometer and Engler Viscometer.

List of Bidders found RESPONSIVE in Technical Bid (Part-I) Evaluation

तकनीकी बोली (भाग-I) मूल्यांकन में उत्तरदायी पाए गए बोलीदाताओं की सूची

Sl. No.	For Items	आइटम के लिए	Name & Address of Bidder(s) बोलीदाता(ओं) का नाम व पता
1	Crushing Value Apparatus		Aimil Ltd. Instrumentation & Technologies
2	Aggregate Impact Tester with Automatic Blow Counter		
3	Los Angeles Abrasion testing machine with Counter		

[Signature]
23/3/13

[Signature]


[Signature]
23/3/13


4	Thickness Gauge	Naimex House, A-8, Mohan Co-operative Industrial Estate, Mathura Road, New Delhi – 110044 INDIA Phone: 91-11-30810200 Fax: 91-11-26950011 Email: info@aimil.com
5	Length Gauge	
6	Universal Penetrometer	
7	Ring and Ball Apparatus	
8	Ductility Testing Machine with digital display	
9	Flash Point (Closed) Pensky-Martens Apparatus	
10	Flash Point (Open) and Fire Point, Pensky-Martens Apparatus	
11	Standard tar viscometer	
12	Engler Viscometer	
13	Digital Marshall Apparatus	


The following observation was made in the case of Annexure-C (Special Technical Terms & Conditions) submitted by M/S AIMIL LTD.

Sl. No..	Point in Tender Document निविदा दस्तावेज में बिंदु	Reasons कारण
1	Point No. 11 Page No. 16/69	AIMIL has accepted the payment conditions as per GCC 22.1 Clause 16(i).

Therefore, the procurement of lab equipments may be considered from AIMIL LTD. after proper attention to the above mentioned point at the time of opening of Financial Bid.


(R.P.Singh)
Professor


(A. K. Sachan)
Professor


(R. P. Tiwari)
Professor & Head

REF: OT-26/MNNIT/Purchase Office/CED/Lab Equipments (UG Lab)/2013-14 Dated 8/02/2013

List of Bidders found NON-RESPONSIVE (along with reasons) In Technical Bid (Part-I) Evaluation

तकनीकी बोली (भाग-1) मूल्यांकन में अनुत्तरदायी (कारणों के साथ) पाए गए बोलीदाताओं की सूची

Sl. No.	Name & Address of Bidder(s) बोलीदाता(ओं) का नाम व पता
1.	Not Applicable (NA)

Reasons for being NON-RESPONSIVE अनुत्तरदायी होने के कारण

Sl. No.	Point in Tender Document निविदा दस्तावेज में बिंदु	Name & Address of Bidder(s) बोलीदाता(ओं) का नाम व पता
	In Tender Document	
	NA	NA

List of Bidders found NON-RESPONSIVE (along with reasons) In Technical Bid (Part-I) Evaluation

तकनीकी बोली (भाग-1) मूल्यांकन में अनुत्तरदायी (कारणों के साथ) पाए गए बोलीदाताओं की सूची

Sl. No.	For Items आइटम के लिए	Name & Address of Bidder(s) बोलीदाता(ओं) का नाम व पता
NA	NA	NA

Reasons as per Technical Specifications तकनीकी निर्दिष्टीकरण के अनुसार कारण

(As given in Chapter-3, Annexure-A, on page no. 106 to 116/156) अध्याय-3, अनुच्छेद-ए, पृष्ठ 106-116/156 के अनुरूप

Sl. No.	Points as per Tender Document निविदा दस्तावेज के अनुरूप बिंदु	Technical Specifications Required आवश्यक तकनीकी निर्दिष्टीकरण	Technical Specifications offered by Bidder बोलीदाता द्वारा प्रस्तुत तकनीकी निर्दिष्टीकरण
1.	NA	NA	NA

(A.) List of Bidders found RESPONSIVE in Technical Bid (Part-I) Evaluation

तकनीकी बोली (भाग-1) मूल्यांकन में उत्तरदायी पाए गए बोलीदाताओं की सूची

Sl. No.	For Items आइटम के लिए	Name & Address of Bidder(s) बोलीदाता(ओं) का नाम व पता
1.	Autoclave (Horizontal)	Matrix Eco Solution 201, Priyanka Tower, Basai Darapur, Industrial Estate, Najafgarh Road, New Delhi-110015.
2.	Hot Air Oven	
3.	Water Bath Rectangular with thermostat	
4.	Autoclave (vertical)	

(R.P.Singh)
Professor

(A.K. Sachan)
Professor

(R.P.Tiwari)
Professor & Head